



PHENIX TOF.W OPERATION PROCEDURE

PHENIX Procedure No. PP-2.5.3.8-07

Revision: A

Date: 2/25/2010

Hand Processed Changes

<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approvals

[Signature] 2/25/10
PHENIX S E & I Date

[Signature] 2-25-10
Cognizant Scientist/
/Activity Manager Date

[Signature] 2/25/10
PHENIX Safety Date

CA-D ES&H/SAFETY Date



PHENIX TOF.W OPERATION PROCEDURE

PHENIX Procedure No. PP-2.5.3.8-07

Revision: A

Date: 2/25/2010

<u>Hand Processed Changes</u>			
<u>HPC No.</u>	<u>Date</u>	<u>Page Nos.</u>	<u>Initials</u>
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

Approvals

_____ PHENIX S E & I Date	_____ Cognizant Scientist/ Date /Activity Manager
_____ PHENIX Safety Date	_____ CA-D ES&H/SAFETY Date
_____	_____

REVISION CONTROL SHEET

LETTER	DESCRIPTION	DATE	AUTHOR	APPROVED BY	CURRENT OVERSIGHT
A	Original Issue	2/25/2010	D. Lynch	D.Lynch, R. Pisani, P. Giannotti	D. Lynch

INTRODUCTION

The Operating Procedures for the PHENIX TOF W. detector subsystem have not been issued as a controlled procedure. Procedural requirements have been codified and are maintained up-to-date by the TOF West group experts on the PHENIX internal website at the following link:

https://www.phenix.bnl.gov/WWW/run/XX/stand_orders/Orders.html#TOF-W

(Note: replace XX by the current run number to follow link)

A link to the current TOF West experts list can be found at the following link.

https://www.phenix.bnl.gov/phenix/WWW/run/XX/contacts/tofw_experts.html

(Note: replace XX by the current run number to follow link)